

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**



Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**







FIG. 3



# GATEWAY DETAILS CUT LINE - 230 222




FIG. 4A

# Video Adapter




FIG. 5



Terayon Confidential Proprietary

# VIDEO ON DEMAND PROCES "PULL" TECHNOLOGY






FIG. 6A

From  
FIG. 6A










FIG. 6D




FIG. 6E

## WIDEBAND INTERNET ACCESS PROCESS




FIG. 7




FIG. 8